

Enjoy the benefits of being an owner/user and occupying between 6,246 RSF and 20,599 RSF (with future expansion options) while also receiving rental income from occupied spaces in a total 29,870 RSF building.

29,870 RSF

Jared Booth, SIOR, CCIM Executive Vice President +1 801 573 5959 jared.booth@colliers.com **Gwen Knight**Executive Vice President
+1 314 422 0467
gwen.knight@colliers.com



Executive Summary

On behalf of Beacon Danbury Corporate, LLC, Colliers is pleased to offer an owner/user opportunity for the 29,870 RSF Building A of Danbury Corporate Park in the thriving municipality of Sandy in Salt Lake County. An owner/user has the opportunity to occupy a portion of the building now while enjoying rental income from the remainder of the building under scenarios described below.

Danbury is a three-building corporate park conveniently located just off of I-15 at 9000 South in mid-Salt Lake County within the municipality of Sandy, approximately 15 minutes south of Salt Lake City Central Business District and 20 minutes from the Salt Lake International Airport. The total park consists of approximately 90,000 RSF in three equally-sized buildings of approximately 30,000 RSF each. Danbury A is the northernmost building within the park and is situated on 1.56 acres.

Danbury is located with an Opportunity Zone, making this an available investment for an Opportunity Zone Fund.

The property has been professionally managed since its original development in 1997. The roof was replaced in 2019 and is under a warranty with 15 years remaining.

Building A is a unique opportunity for an owner/user to currently occupy between 6,246 RSF and 20,599 RSF, while enjoying rental income on the remaining square footage.

Property Summary		
Total Square Feet	29,870 RSF	
Land Size	1.56 AC	
Parking	4/1,000	
Zoning	CR - PUD- Regional Commercial Opportunity Zone	
Purchase Price	\$8,000,000 (\$268/RSF)	



Owner/User has options regarding owner/user occupancy:

Occupy 20,599 RSF (14,353 RSF entire 1st floor plus 6,246 RSF 2nd floor southeast corner) and enjoy immediate monthly gross rental income from two secondfloor tenants.

Occupy 6,246 RSF (2nd floor southeast corner) and enjoy immediate monthly gross rental income from three leased spaces.



Property Summary

Address	8851 S. Sandy Parkway Sandy, UT 84070	
Use	Office	
RSF	29,870	
Levels	2	
Elevators	1 (hydraulic, US Elevator)	
Year Built	1997	
Acreage	1.56	
Real Estate Tax Parcel #	27-01-176-013-0000	
Real Estate Taxes 2023	\$44,432.12	
Governing Municipality	Sandy, UT	
Zoning	Opportunity Zone	
	CR-PUD (Regional Commercial - Planned Unit Development District)	
Property Manager	Colliers Real Estate Management	
Construction Type	Concrete tilt up	
Building Surface	Integral color concrete	
Roof		
Rubber Membrane	60-mil PVC single-ply membrane by Sika Sarnafil	
Age of Roof	Roof replaced in 2019 20-year warranty	
Air Conditioning		
# AC units	5 rooftop	
Capacity or Tons/unit	Two (2) 30-ton units; Two (2) 20- ton units; One (1) 1/4-ton unit	

Heating Systems	
# of units	1
Boiler Natural Gas	19.1 HP
Type	Variable Air Volume (VAV)
	System (36 VAV boxes)
Water Heaters	
# of units	1
Electric or Gas	Gas
Capacity	100 gallon
Age of units	1998
Power	
Provider	Rocky Mountain Power
Single phase	Yes
Three phase	Yes
High power capacity	800 Amp / 480 V / 3-phase
Other	UPS & generator backup (partial)
Natural Gas	
Provider	Dominion Energy
# meters	1
Meter sizes	2 lb.
Security System	
External and internal access control	Per tenant (generally key card access to suites)
Parking	4/1,000
	Tenants have access to parking throughout park

Fire Supression	
Wet or Dry	Wet for most of the building, dry for Verizon server room
Monitored system	Yes
Monitoring provider	Certified Fire Protection
Maintenance or comments	Inspected 2x per year
Communication Provider	Verizon/Comcast
Communication Type	Fiber/Cable/Wired for Cat 5 or 6
Landscape Sprinkler System	Yes - automatic
Restrooms	Restrooms on both floors have been renovated






Danbury Corporate Park

This property's location is second to none, conveniently located near numerous amenities, bus and rail public transit stops and immediately west of the 9000 South and I-15 interchange with over 45,000 and 195,000 ADT respectively.



Drive Time Destination	Minutes
Salt Lake City's Central Business District	15
Salt Lake City International Airport	20
Silicon Slopes	20




Level 1 - 14,353 RSF






Level 2 - 15,517 RSF






Area Map





Area Amenity Map





Danbury Corporate Park Bldg $A \mid 10$













Sandy Overview



Yes, Utah!

Utah is a national leader in high job growth, low unemployment, low cost of doing business, and talented labor. The state regularly ranks among the best states for business, careers, living, health, and quality of life. Utah provides an array of employment opportunities in various industries and offers its residents numerous lifestyle options that range from quiet rural settings to thriving urban centers.

Utah is world-renowned for its bounty of public lands and year-round recreational opportunities ranging from mountain wilderness to desert landscapes. Utah has five national parks, six national forests, numerous state parks and recreation areas, and is home to "The Greatest Snow on Earth" with over a dozen ski resorts.



96,994



34,107







Best Economic
Outlook
Rich States Poor States
(2024 - 17th year in a row)

Best State to Start a
Business
WalletHub
(2024)

Best State & Best Economy U.S. News & World Report (2023)

SLC Intl Airport

#5On-time flights and partures in N. Amer

departures in N. America
U.S. News & World Report
(2023)



Danbury Corporate Park Building A 8851 S. Sandy Parkway | Sandy, UT 84070

Jared Booth, sior, ccim Executive Vice President +1 801 573 5959 jared.booth@colliers.com

Gwen KnightExecutive Vice President +1 314 422 0467 gwen.knight@colliers.com

Colliers

111 S. Main St., Suite 2200 Salt Lake City, UT 84111 Main: +1 801 947 8300 colliers.com



This document has been prepared by Colliers International for advertising and general information only. Colliers International makes no guarantees, representations or warranties of any kind, expressed or implied, regarding the information including, but not limited to, warranties of content, accuracy and reliability. Any interested party should undertake their own inquiries as to the accuracy of the information. Colliers International excludes unequivocally all inferred or implied terms, conditions and warranties arising out of this document and excludes all liability for loss and damages arising there from. This publication is the copyrighted property of Colliers International and/or its licensor(s).

©2024. All rights reserved.