

Danbury Corporate Park

8851-8911 S. Sandy Parkway | Sandy, Utah 84070

Available

• **Building A** Suite 210 - 2,686 RSF 2nd Floor Suite 220 - 6,246 RSF

• Building B Suite 100 - 5,033 RSF 1st Floor

• **Building C** Full Floor - 15,258 RSF 2nd Floor

Property Highlights

- Move-in ready
- Furnishings available.
- Unparalleled central valley location with immediate I-15 access at 9000 South
- Fiber optic connectivity
- Floor to ceiling glass windows
- Parking ratio: 4.5/1,000

Available:

Building A 2,686 RSF

6,246 RSF

Building B 5,033 RSF Building C 15,258 RSF

Lease Rate:

\$18.50 - \$19.50/RSF


Full Service (Less Janitorial)

colliers.com

Floor Plan

Building A: Suite 210 2nd Floor Suite 220

2,686 RSF Available 6,246 RSF Available







Danbury Corporate Park A












Floor Plan

Building B: Suite 100

1st Floor

5,033 RSF Available








8851 S. Sandy Parkway | Sandy, UT

Danbury Corporate Park B












Floor Plan

Building C: Full Floor 2nd Floor

15,258 RSF Available









Multi-Tenant Floor Plan

Building C: Potential Multi-Tenant Configuration 15,258 RSF Available 2nd Floor








Danbury Corporate Park









Jared Booth, sior, ccim Executive Vice President +1 801 573 5959 jared.booth@colliers.com

Gwen Knight Executive Vice President +1 314 422 0467 gwen.knight@colliers.com **Colliers**

6440 S. Millrock Dr., Suite 500 Salt Lake City, UT 84121 Main: +1 801 947 8300 colliers.com



This document has been prepared by Colliers International for advertising and general information only. Colliers International makes no guarantees, representations or warranties of any kind, expressed or implied, regarding the information including, but not limited to, warranties of content, accuracy and reliability. Any interested party should undertake their own inquiries as to the accuracy of the information. Colliers International excludes unequivocally all inferred or implied terms, conditions and warranties arising out of this document and excludes all liability for loss and damages arising there from. This publication is the copyrighted property of Colliers International and/or its licensor(s). ©2024. All rights reserved.